

4

3

2

1

D

D

C

C


B

B

A

A

PARTS LIST		
ITEM	QTY	PART NUMBER
1	1	WM200-1WDS-H
2	2	WM200-3-500-S-F-1
3	2	WM200-4-500-187-B-1
4	2	WM200-12
5	6	LW8YZ 038
6	6	FCS 038 0125 24
7	1	WM625150HM
8	1	WM6251250HM
9	4	SAEFYZ8 050
10	1	H5Z 050 0550 13
11	1	H5Z 050 0600 13
12	3	HNNYSZ 050 13
13	2	WM200-9CB
14	2	SHCZ 031 0200 18
15	2	HNNY8Z 031 18
16	2	WM200LEVEL
17	1	H8Z 050 0350 13
18	1	HNNY8Z 050 13
19	1	MB2 050 14
20	1	WM200-7-1
21	1	WM200-7-1-125-MS
22	3	H8Z 044 0200 20
23	3	HNNY8Z 044 20
24	2	WM200-8S
25	1	H5Z 050 0225 13
26	6	H8Z 038 0075 24
27	1	WM200-8C
28	2	WM625200HM



**PROPRIETARY AND CONFIDENTIAL**

THE INFOTMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF WEHRS MACHINE & RACING PRODUCTS. ANY REPRODUCTION IN PART OR AS A WHOLE WITHOUT WRITTEN PERMISSION OF WEHRS MACHINE & RACING PRODUCTS IS PROHIBITED

<b>DRAWN</b>	B. Steinberg	8/31/2021
<b>PROGRAM #:</b>		
<b>CYCLE TIME:</b>		
<b>MATERIAL</b>		
<b>SAW LENGTH</b>		



TITLE		
SIZE C	PART NO WM200WDS-H-0	REV
SCALE	SHEET 1 OF 1	

