

# ATTENTION!

This carburetor is specifically calibrated for supercharged applications. The power valve is referenced for a manifold vacuum. The fitting shown in the figure below, is the reference port for the power valve. A vacuum hose must be connected from this fitting to a vacuum source on the lower manifold. Failure to connect this port to a manifold vacuum will allow the power valve to remain open at idle, causing an excessively rich fuel mixture.



Connect a vacuum hose from this fitting to a vacuum source on the lower manifold.

199R-10171  
Date: 5-18-00

# ATTENTION!

This carburetor is specifically calibrated for supercharged applications. The power valve is referenced for manifold vacuum. The fitting shown in the figure below, is the reference port for the power valve. A vacuum hose must be connected from this fitting to a vacuum source on the lower manifold. Failure to connect this port to manifold vacuum will allow the power valve to remain open at idle, causing an excessively rich fuel mixture.



Connect a vacuum hose from this fitting to a vacuum source on the lower manifold.

199R-10171  
Date: 5-18-00